Material Safety Data Sheet
May be used to comply with
OSHA's Hazard Communication Standard,
29 CFR 1910.1200. Standard must be
consulted for specific requirements

U.S. Department of Labor

Occupational Safety and Health Administration (Non-Mandatory Form)



29 CFR 1910.1200. Standard must be consulted for specific requirements.

IDENTITY (As Used on Label and List)

EA 934NA Part A

(Non-Mandatory Form)

Form Approved

OMB No. 1218-0072

Note: Blank spaces are not permitted. If any item is not applicable, information is available, the space must be marked to indicate

EA 934NA	TPart A	informat	ion is available, the sp	ace must be m	not applicable, or no added to indicate that	
Section I						
Manufacturer's Name	3	I Family		:		
Hysol Aerospace & Industrial		Emergency Telephone Number				
Address (Number, Street, City, State, and ZIP Code)		(415) 687-4201 Telephone Number for Information				
2850 Willow Pass Road	(415) 687÷4201 X362 X319					
Pittsburg, CA 94565	Date Prepared 5/4/87	Date Prepared				
•			reparer (optional) Franz		:	
Section II — Hazardous Ingredients/Ident	ity Informatior		Established	NA=Not	Available	
Hazardous Components (Specific Chemical Identity; Co	OSHA PEL	ACGIH TLV	Other Lin Recommer			
4-Glycidyloxy-n,n-diglycidylan	iline				70 (Optional)	
(CAS# 502					. 25	
Silica (CAS# 7631-86-9)	<u> </u>				< 35	
Aluminum powder (CAS# 7429-90-	EV	20 mppcf			< 15	
Trainfian powder (CAS# 7429-90-	5)		5 mg/m ³		< 30	
	•					
	· · · · · · · · · · · · · · · · · · ·					
	\$					
				*		
Section III — Physical/Chemical Characteri	·					
Boiling Point	Stics					
soming Point	Decomposes	Specific Gravity	$(H_2O = 1)$			
/apor Pressure (mm Hg.)	Decomposes				>1	
,	< 0.01mm	Melting Point			N1.0	
apor Density (AIR = 1)		Evaporation Rate			NA	
		(Butyl Acetate =			Nil	
olubility in Water Ni 1	· ·				1 11 1	
ppearance and Odor						
Viscous grey paste	with sliak	it odor	,			
		10 0001				
ection IV — Fire and Explosion Hazard Da ash Point (Method Used)						
>300°F NE	Flammable Limits		LEL	UEL ·		
ktinguishing Media			NA			
Dry chemical or Halon fire ext pecial Fire Fighting Procedures	inguisher.	or water s	pray, foam or	fog.		
Use self-contained breathing a	pparatus wh	ıen fiahtin	a finac i-			
serviting a	PPUI UCUS WI	ion righth	A TILES IN CO	ntined ar	eas.	
Negral Fire and F		<u> </u>				
nusual Fire and Explosion Hazards Dense smoke and toxic gasses m	av ho 146-					
smoke and toxic yasses in	ay be liber	aced.				
•						

EA 9341				<u> </u>		
	- Reactivit	y Data				
Stability	Unstable		Conditions to Avoid			
	Stable	Х				
Incompatibili	ity (Materials.to	Avoid)	strong Lewis or m			
. Hazardous De	SCUMPOSITION OF	Byproducts				
CO NO	lx. aldehy	des, acids	and undetermined	lorganics.		
Polymerization	1 May Occu	r x	Conditions to Avoid Ayoid	mixing resin a	nd curing agent in	batches
· .	Will Not O	ccur	unless curing sur	faces to be bon	nd curing agent in ot heat mixed adhe ded. Failure to ob ld-up with the rel	<u>sive above</u> serve cauti
Section VI	— Health H	azard Data	may result in exc	<u>essive heat bui</u>	ld-up with the rel	CUSC OF COX
Route(s) of En		Inhalation?	S	kin?		gasse
Health Hazard	s (Acute and Ch	yes ronic)		ye?s	Ingestion?	
May cau	se skin ir	rritation	and possible alle	rgic reactions.	Prolonged and repo	eated
<u>contact</u>	may cause	e sensitiz	ation which will	result in aller	gic reactions.	
-		•		·		· ·
Carcinogenicity	/:	NTP?	IA	RC Monographs?	OSHA Regulated?	-
				no	no	
Signs and Sym	ptoms of Expos	sure				
Skill ras	sh, irrita	tion				
Medical Conditi	ions					
Generally Aggra	avated by Expos	sure				
NA			•			
Flush s	First Aid Proce	dures ye contact	with plenty of v	vater Wash skir	n thoroughly with s	
water,	rubbing a	Icohol or	hand cleaner Do	not use solvent	s. Remove soiled o	oap and
Section Att	— Precautio	ins for Safe I	Handling and Use W	vash before reus	e. It irritation p	Hothing and
Steps to Be Tal	ken in Case Mat	lerial Is Released	or Spilled		e up and transfer	
contain	er. Wipe	up remaini	ng residue with s	colvents observ	ing solvent flamma	to metal
caution	ıs.		Jac Widn 5	OTACHES ODSERV	ing sorvent framma	Dility
Waste Disposal	Method	zandoue wa	sto populing t	507 1		
dispose	of 20 00	zaruous wa	ste according to	DOI hazard clas	s. If not regulate	d by DOT,
Precautions to B	of as ORI le Taken in Han	dling and Storing			· ·	
Keep co	ol in acco	ordance wi	th label instruct	ions.		
<u> </u>						
Other Precaution Follow	s recommende	ed curing :	schedule.			
			- Circumstance	•		
Section VIII -	- Control M	easures				
lespiratory Prote	ction (Specify Tu	mel				
Not need	ded with a	tood indust	trial ventilation		• ·	
		Recommende	ed	Special		
	Mechanical (Ge	<i>neral</i>) Recommende	ed	Other		
otective Gloves Impervio	ous plasti	c or rubbe	N E	ye Protection	-	
ther Protective C	Clothing or Equip	oment Oct chin -	and clothing	afety glasses o	or goggles	F
ork/Hygienic Pra	actices	CCC 2KIII d	ing Crouning		·	
NA						
	•		Page 2			

+ USGPO: 1986-491-529/45775